

Quotation Number:	RFQ202011/008
Description:	INSPECTION AND REPAIR OF AN ESCO PCR CABINET
Bid Closing Date:	17/11/2020 @12:00pm
Compulsory Briefing Session:	Optional
Plant Address:	ERWAT Scientific Services Hartebeestfontein Office Park Bapsfontein Road (R25) Kempton Park 1631
Contact Person	Nico van Blerk or Phillip Thobejane
Contact Number	(011) 929 7167 or 7014
Validity period	3 Days

INTRODUCTION:

The ERWAT Scientific Services Department currently has one ESCO PCR Cabinet (Model: Airstream PCR-3A, Serial number: 2011-61461) operating at its laboratory. The unit is faulty and requires repairs including parts for it to become operational again.

GENERAL REQUIREMENTS AND SCOPE OF WORKS:

Potential bidders will be required to visit the ERWAT laboratory where the unit is located.

Potential bidders are hereby invited to provide a quotation for the following:

INSPECTION OF AN ESCO PCR CABINET TO PROVIDE A FULL QUOTATION FOR REPAIRS NEEDED

- Inspect and evaluate a non-operational ESCO PCR Cabinet (Model: Airstream PCR-3A, Serial number: 2011-61461).
- Please provide a full quotation for parts and repair work needed as well as the following:
 1. Strip and quote rate per hour
 2. Km rate per hour (limited to AA rates)
 3. Estimated value for parts (worse-case scenario)
- All the above line items will be evaluated for comparative purposes to establish the highest scoring bidders.
- However, bidders should note that ERWAT will issue a purchase order (PO) for the strip and quote first. The bidder will be required to give a breakdown for the estimated value for parts to receive an updated PO for the parts and final repairs.
- The total offer shall not be exceeded and only actuals will be paid.
- Bidders are required to submit a minimum of 6 - 12 months warranty/guarantee on works and parts replaced.

VERY IMPORTANT:

- Bidders or technicians to perform the evaluation and/or repairs **MUST** be trained and qualified to perform repairs on ESCO brand cabinets.

- Please provide proof of qualifications and training completed.
- Failing to provide proof of ESCO training and qualifications may lead to disqualification.

Please e-mail your quotations with supporting documents to rfq@erwat.co.za